



Affected area of marsh environment near Garden Island Bay, Louisiana. Source: US Coast Guard

**INCIDENT OVERVIEW**

**WebEOC Incident:** 25-015 Well #59 Oil Spill - Plaquemines - 27APR  
**Activation Level:** CAT – Level 4  
**State Declaration:** N/A

**INCIDENT OBJECTIVES**

1. Ensure the safety of all individuals present, including public, first responders, and emergency personnel involved in response
2. Coordinate with ESFs to ensure consistent resource sharing and response
3. Maintain effective communication channels to disseminate information to the public, first responders, and emergency personnel involved in response
4. Protect the environment, wildlife, fishing industry, and coastal infrastructure
5. Adapt objectives based on changing incident conditions to maintain response

**WEATHER**

**Today:**

Sun/cloud mix, 20% chance of thunderstorms/showers, highs in the low/mid 80s SE winds 5-15mph, gusts 15-20mph. High Tide 1.6ft at 1246.

**Overnight:**

Becoming fair, lows around 70, SE winds 5-10mph. Low Tide 0.1ft as 0112.

**Tomorrow:**

40% showers and thunderstorms, highs in the low/mid 80s, SE-to-S winds 5-10mph, gusts to 15mph. High Tide 1.5ft at 1353.

**OPERATIONAL RHYTHM**

**Coordination Call/Intel Briefing:** N/A  
**Parish and ESF SITREPs due in WebEOC:** 0800  
**SITREP published:** 0900

**Trend Legend:**

- ↑ Improvement Noted
- ↓ Worsening Situation
- No Change

**Lifeline Color Description:**

- Green (GN)** – Minor disruptions or limitations to the community
- Yellow (YL)** – Disruptions affect delivery of services and resources
- Red (RD)** – Severe challenges and obstacles hindering essential services
- Grey (GR)** – Unknown status



Lifelines Summary	
HazMat ↓	<p><b>Plaquemines Parish</b></p> <ul style="list-style-type: none"> <li>• Will continue to monitor ongoing operations</li> </ul> <p><b>LANG</b></p> <ul style="list-style-type: none"> <li>• Monitoring and standing by for potential missions if required</li> </ul> <p><b>LDWF</b></p> <ul style="list-style-type: none"> <li>• Wildlife Hotline has been established for this incident and is currently being monitored by Wildlife Response Services (WRS). Hotline# (832)514-9663</li> <li>• 4 wildlife biologist personnel on standby for future response operations for the Rehab Center and Field Wildlife Response Survey</li> <li>• The heavily oiled area near the well is still unsafe to conduct wildlife response</li> <li>• A wildlife response team will survey the impact area to search for impacted wildlife and gather info for the development of a response plan; The survey will determine initial equipment and personnel needs that will lead to an expanded response on 1 MAY 2025 and beyond</li> </ul>

Lifelines Summary	
Food, Hydration, Shelter →	<ul style="list-style-type: none"> <li>• No incidents reported</li> </ul>
Health and Medical →	<ul style="list-style-type: none"> <li>• No incidents reported</li> </ul>
Energy →	<ul style="list-style-type: none"> <li>• No incidents reported</li> </ul>
Communications & Cyber →	<p><b>Comms</b></p> <ul style="list-style-type: none"> <li>• 150 out of 150 LWIN towers sites are in wide-area operations</li> <li>• No requests for assets or support</li> <li>• Monitoring Situation</li> </ul>
Transportation →	<ul style="list-style-type: none"> <li>• No incidents reported</li> </ul>
Water Systems →	<ul style="list-style-type: none"> <li>• No incidents reported</li> </ul>
Safety & Security →	<ul style="list-style-type: none"> <li>• No incidents to report</li> </ul>